


# **SPECIAL AIRWORTHINESS INFORMATION BULLETIN**

REGULATORY SUPPORT DIVISION  
P.O. BOX 26460  
OKLAHOMA CITY, OKLAHOMA 73125-0460



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

No. CE-00-30  
August 2, 2000

*SAIB's are posted on the internet at <http://av-info.faa.gov>*

---

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

## **Introduction:**

The purpose of this Special Airworthiness Information Bulletin (SAIB) is to provide safety information to owners and operators of the Wytwornia Sprzetu Komunikacyjnego Model PZL-104 WILGA 35 on the following:

- HORIZONTAL STABILIZER CONNECTORS

This SAIB is only advisory in nature and not mandated by regulation.

## **Background:**

The FAA has received a Mandatory Bulletin from PZL Okecie that requires replacement of the Horizontal Stabilizer Connector, Part Number CE360051 and Spacing Busher CE360052. If the connector fails, longitudinal pitch control could be lost resulting in the loss of control of the airplane.

## **Recommendation:**

The FAA highly recommends that you comply with the attached Mandatory Bulletin.

## **General Information:**

The FAA provides this information as a courtesy to PZL-04 Wilga 35 owners/operators because this is a significant potential safety issue. The FAA does not issue Airworthiness Directives for airplanes that do not have a U.S. type certificate. This safety issue will not be tracked or enforced by the FAA. Furthermore, the FAA will not use an SAIB to track all safety related items for non-type certificated products.

## **Further Information Contact:**

Roman Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri, 64106; telephone (816) 329-4141; Facsimile (816) 329-4090.